




Fields of Gold

Merchandise Fitting Instructions

T- Shirts and Hoodies



1. Lay a T-shirt or Hoodie that fits you flat on the table.
2. Measure across the chest, at a point just below the where the bottom of the sleeve joins the body of the garment. This is the 1/2 Chest Measurement.
3. Measure from a point at the centre of the back of the shirt, from where the collar meets the body of the shirt down to the hem line. This is the CBL (Centre Back Length).

*All Measurements are in centimetres.

Sizing Charts

Hoodies

Size	2XS	XS	S	M	L	XL	2XL	3XL	4XL	5XL	6/7XL
1/2 Chest	51.5	55	57.5	60	62.5	65	67.5	70	72.5	75	80
CB LENGTH	62.5	66.5	70.5	72.5	74.5	76.5	78.5	80.5	81.5	82.5	84

T-shirts

Size	S	M	L	XL	2XL	3XL
1/2 Chest	47	52	56.5	61	64	68
CB LENGTH	71	75	78.5	82	83.5	85

Please note:

1. All measurements are in cm
2. Due to the nature of production there may be a 1.5 cm variation in sizing